## **ATA 95s**





00	Banana Cable – 1 2m	1 black & 1 red	Non twisting cable extension with 4.0 mm banana socket connection.	
rOvOr	Stacking Banana Cable – 1.2m	1 black & 1 red	Non twisting extension cable with branch out connection.	
	0.8mm Flat Test Lead to Female Banana Socket	3 male, 3 female	Used on 0.8 mm flat terminal output connection.	
	1.2 mm Flat Test Lead to Female Banana Socket	4 male, 4 female	Used on 1.2 mm flat terminal output connection.	
	2.0 mm Flat Test Lead to Female Banana Socket	4 male, 4 female	Used on 2.0 mm flat terminal output connection.	
E	2.5 mm Flat Test Lead to Female Banana Socket	3 male, 3 female	Used on 2.5 mm flat terminal outpo connection.	
	3.0 mm Flat Test Lead to Female Banana Socket	4 male, 4 female	Used on 3.0 mm flat terminal outpo connection.	
	5.0 mm Flat Test Lead to Female Banana Socket	3 male, 3 female	Used on 5.0 mm flat terminal output connection.	
N N	6.0 mm Flat Test Lead to Female Banana Socket	3 male, 3 female	Used on 1.5 mm round terminal output connection.	
	1.5 mm Round Test Lead to Female Banana Socket	3 male, 3 female	Used on 6.0 mm flat terminal output connection.	
1	2.0 mm Round Test Lead to Female Banana Socket	3 male, 3 female	Used on 2.0 mm round plate terminal output connection.	
	3.5 mm Round Test Lend to Fernale Banana Socket	3 male, 3 female	Used on 3.5 mm round terminal output connection.	
	4.0 mm Round Test Lead to Female Benene Socket	3 male, 3 female	Used on 4.0 mm round terminal output connection.	

CZ SINCRO

## KIT DI ADATTATORI PER MISURE ELETTRICHE

- Serie completa di adattatori e dispositivi per misure su sensori e attuatori. Semplifica e velocizza le misure con i tester in tuo possesso, consentendo la ricerca dei guasti in un numero sempre maggiore di sensori ed attuatori elettronici che equipaggiano i veicoli di nuova generazione.
- Il Kit contiene in totale 95 pezzi, adatti per ogni tipo di contatti di cui sono dotati sensori e attuatori. Una valigetta per il trasporto, di peso contenuto (1.7Kg), consente di mantenere in vani adequati e in ordine ogni adattatore.
- Questo Kit è un aiuto prezioso per l'operatore che esegue una ricerca e una verifica specifica di guasti segnalati da lettori di codici difetto o difficili da verificare con la normale dotazione degli strumenti di uso comune.
- Ideale per uso con multimetri ed oscilloscopi.

Per maggiori informazioni visitare il ns. Sito internet: For more information please visit our website:

http://www.sincro.com

Contents								
Photo	Description	Qty	Application					
	Pleroing Clip	1 block & 1 red	Pierce through insulated wires without cutting or stripping its insulation for quick and easy of making contact.					
=	Tend Proben	1 black & 1 rad	Detachable fast probes allow easy cable extension during testing.					
*	Aligator Clips	1 block & 1 red	Ideal for battery terminals or clip connections.					
	Variable resistor with diel indicator (10KD ± 10%)	1pc	Now veriable resistor with dial indicator. Quick and easy way of resistance adjustment without the high of a multi-motor dashing simulation in inestance related services circuit.					
	Polarity/Public Chicker	1pc	Red or Green LED will light up when contact is mode to determine the powrty. (LED turn red for reverse polarity, LED turn green for correct polarity).					
•	LED Stroboscope	2 pcs	For checking a series of terminals in connect withing. Also for pathel or signal compensors between injection (LED turn red for revenie polarly, LED turn green for correct polarity).					
•	3-way Extension	2pcs	Female Banana socket to Dual Male Banana Plug conventor. One to two way connections.					
AÀ	ArtingSFS Simulator	Spcs	Used to confirm SRS Airbag power input by connecting it find to check for any short direct before installing a new SRS unit. (Note 2 pcs each of 20, 22 8 2 7 0 resistes an provided.)					
	Most Fusus Adapter	1pc	Power branch out adapter for Mass fizie.					
-	ATC Fune Adepter	1pc	Power branch out adapter for ATC flare. The new design enables the user to use the same fuse taken from the tase box in order to flave. The right emperage during testing.					
-	Mm Fune Adapter	1pc	Power branch out adapter for Mini- tuse. The new design enables the user to use the same fuse taken user to tuse box in order to have the right emperage during testing.					
		2pcs	Ideal for probing connectors with small gauge wires from the					

Normal		Other Supplier		
Iben	Photo/Qty	2tem	Photo/Qty	
Plencing Clip	2 pc	no	no	
Maxi Fuse Adapter	18	no	no	
ATC Fuse Adapter (New Design)	18	no	no	
Mini Fuse Adapter (New Design)	1 pc	no	no	
Polarity/Pulse Checker	1 pc	no	no	
Variable resistor with dial Indicator - 10KΩ ± 90% (New Design)	1 pc	Verible Resistor	2 pcs	
LED Stroboscope	<b>C</b> C	LED Examing Light	2 pcs	
3-way Extension	<b>\$</b>	one to two form	2 po	
Airbeg/SRS Simulator	2003	SRS Replacing ang Testing Device	2 pcs	
Probe with Cap	200	Measure Stick	2 pcs	
Aligator Clip	*	Crocodile Clip	2 pos	
Actoular Probe	2 pcs	Various Type of Probes	4 pcs	
Banana Cablet.2m	O <sub>K</sub> O <sub>k</sub>	One to one form	-	
Stacking Ranana Cable 1.2m	ONO		4 pcs	
Flat Test Lead (Male and Female: Sizes 0.8, 1.2, 2.0, 2.5, 3.0, 5.0, 6.0)	400	Flat Shape Connector	11111	
Round Test Lead Male and Female: Stres 1.5, 2.0, 3.5, 4.0)	A pos	Round Shape Connector	1111	
Packaging	Light Weight EW Carry Case - 1,74 kg / 2,1 kg	Packaging	Heavy Plantic Case - 2-42 kg / 3kg = 41 x 3	

